


TEST REPORT

Lightwater Quarries Ltd
Potgate Quarry
North Stainley
Ripon
HG4 3JN



White
Rose
Laboratory
Services
Ltd

Lumley St • Castleford • WF10 5LB
01977 520625 • enquiries@whiteroselabs.co.uk

Report WRL/17/2971wa
Issue date 19/12/17

Material	Crushed limestone aggregate 4/20mm 2:1 lab blend		
Site	Potgate Quarry		
Specification	EN 12620 4/20 $G_C90/15 f_4$	Sample N°	S/17/2971
Source	Potgate Quarry	Sampled by	S Tallentire/L Rowling
Supplier	Lightwater Quarries Ltd	Date sampled	11/12/17
Sample location	End of belt	Date received	11/12/17
Sample type	Bulk	Date tested	17/12/17
Order number	8815LQ	Date reported	19/12/17

BS EN 1097-6 2013 Water absorption

Clause 8 Pyknometer method

Fraction tested 4 - 31.5 mm

Water absorption

WA_2

2.9 %

A handwritten signature in black ink, appearing to read 'J Church'.

J Church
Managing Director