


# TEST REPORT

Lightwater Quarries Ltd  
Potgate Quarry  
North Stainley  
Ripon  
HG4 3JN



White  
Rose  
Laboratory  
Services  
Ltd

Lumley St • Castleford • WF10 5LB  
01977 520625 • enquiries@whiteroselabs.co.uk

Report WRL/17/2976tpfv  
Issue date 02/01/18

Material	Crushed Limestone 6F5	Sample N°	S/17/2976
Site	Gebdykes Quarry	Sampled by	ST / LR
Specification	DTP SHW Series 600 6F5	Date sampled	11/12/17
Source	Gebdykes Quarry	Date received	11/12/17
Supplier	Lightwater Quarries Ltd	Date tested	19/12/17
Sample location	Stockpile	Date reported	02/01/17
Sample type	Bulk		
Order number	8815LQ		

## BS 812-111 1990 Ten per cent fines value

Material was tested in soaked condition

10% fines value 120 kN

M Randerson  
Laboratory Services Director